



- Crew Chief Summary:





Pasted from <[http://www-bd.fnal.gov/mcr/plots/24hr\\_plot\\_Accelerators\\_6\\_53\\_31.png](http://www-bd.fnal.gov/mcr/plots/24hr_plot_Accelerators_6_53_31.png)>

- \$21s would not ramp. \$29's were 20 seconds apart, locking at 8 GeV.
- A:LQ!!!
- 
- **Notes from Run Coordinator:**
  - Quiet overnight.
  - Ran well.
  - CDF/D0 access, Shot setup
- **Machine Summaries:**
  - **Linac**
    - Summary:
      - Source current down to 32mA
      - Experts will turn back up
    - Requests:
      - 1 hr access to make NMR proble work
  - **Booster**
    - Summary:

- Running well
    - Tried pushing higher intensity. Effort will continue to day
    - Gamma-T studies
  - Requests:
    - Pre-acc notching \$1d
    - 2-3 hours to repair chopper off tube.
- **Main Injector**
  - Summary:
    - Lifetime on pbar transfers - in minidip and counter wave also.
    -
  - Requests:
    - Clean up reverse injection on shot setup.
    - Reboot LLRF - helps with slip stacking studies.
    - Linux I50 and I52 certificatoin
    - Install MI60S today?
- **Pbar**
  - Summary:
    - Pbar Stacking Numbers
      - ◆ Best Stacking = 13.8 mA/hr,
      - ◆ Production = 15 e-6/proton
      - ◆ Beam on Target = 6.1e12
    - Stacking is up by 5-7 %,
      - ◆ Beam on target increase
      - ◆ Quality of beam is better.
      - ◆ QS732 also repaired
    - Shots - transfer efficiency 86-90% to MI, 85-87% to RR.
    - Problems
      - ◆ A:LQ contactor after access
    - Access
      - ◆ QS732 replaced
      - ◆ Added 10dB to core 4-8GHz momentum cooling
      - ◆ HL amp replaced in core vertical band 1 - was off, but turned back on, caused core to go coherent. Confused the VSA on next shot to RR. Will get this phased today.
      - ◆ During hysteresis ramps. The skew quad settings got changed. Had different coupling and tunes. Disabled the ramps so they wont ramp again
    - Accumulator horizontal damper putting out a lot of power. Both the high band and low band amps. Will troubleshoot today
  - Requests:
    -
- **Tevatron**
  - Summary:
    - Runs fine for last 24 hours.
    - Next store have tune changes for squeeze.
    -
  - Requests:
    - Next shot setup, want to do closure program test to accommodate the MI BPM upgrade.
- **Recycler**
  - Summary:
    - will turn off e- cooling during mining stage.
  - Requests:
    - Two sets of studies to schedule
- **SY120**
  - Summary:
    - Running OK
    - 3 or 4 quad supplies that need adjusting.

- Requests:
      -
  - **MiniBooNE**
    - Summary:
      - Running steady.
      - Rate dropped.
      - HVAC - NE AC unit does not stay on. Want to fix before the weekend. Will do on Thursday.
    - Requests:
      -
  - **NuMI**
    - Summary:
      - Initial cleanout of rosen beads was not completely successful. Will have to do iterations. Could be back by Friday
    - Requests:
      - 
      -
  - **CDF**
    - Summary:
      - 4018 - 87%
      - Integrated luminosity was good.
      - Access - replace Si power supply that is causing problems.
      - Work on muon HV issues
    - Requests:
      -
  - **D0**
    - Summary:
      - 82% efficiency
      - Pre-amp trip. Try to switch other pre-amp, may not help if it is in the harness instead of the PS itself.
      - Took special runs to look at muon rate
      - Access - putting in test PDT to look at lower freq. rate on that.
      - Ramping down solinoid to look at PS for solinoid - dripping water.
    - Requests:
      -
  - **SDA**
    - Summary:
      -
    - Requests:
      -
  - **Mechanical**
    - Summary:
      -
    - Requests:
      -
  - **Other**
    - Summary:
      - FESS clean F0 pond stainer this morning.
    - Requests:
      -
- **The Plan**
  - Summary:
    - CDF/D0 2 hour access
    - Shot Setup - extra time for closure work.
    - One more transfer to RR at 10:30
  - Requests:
    -